

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report ☐ Final Report

Name of Company Fairway Resources Operating LLC	Contact Matt Eagleston
Address 538 Silicon Drive Suite 101 Southlake, Texas 76092	Telephone No. (817) 416 1946
Facility Name South Red Lake II Unit 31	Facility Type Well Location

Surface Owner BLM	Mineral Owner BLM	Lease No. LC-028755A
-------------------	-------------------	----------------------

3001500644

**LOCATION OF RELEASE**

Unit Letter N	Section 35	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release Produced Water	Volume of Release unknown	Volume Recovered 0
Source of Release Flowline Release	Date and Hour of Occurrence Unknown	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Flow line failed causing an unknown volume of produced water to be released. During initial response activities the flow line was clamped and soil is being excavated.

Describe Area Affected and Cleanup Action Taken.\*  
Release site will be remediated to NMOCD Artesia District Office requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: John J. Pulte	Approved by District Supervisor. 	
Title: Operations Engineer	Approval Date: 4-8-10	Expiration Date: 6-8-10
E-mail Address: jpulte@fairwayresources.com	Conditions of Approval.	Attached <input type="checkbox"/>
Date: 2/25/10	Phone: 817-416-1946	

\* Attach Additional Sheets If Necessary

