

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Fairway Resources Operating LLC	Contact	Matt Eagleston
Address	538 Silicon Drive, Suite 101, Southlake, Texas 76092	Telephone No.	(817) 416 1946
Facility Name	South Red Lake II Unit 30	Facility Type	Well Location
Surface Owner BLM	Mineral Owner BLM	Lease No.	NML C 028755A

3001501222

**LOCATION OF RELEASE**

Unit Letter "O"	Section 35	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
--------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Water / Crude Oil	Volume of Release	Unknown	Volume Recovered	0
Source of Release	Daily Operations	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Historic crude oil and produced water impact was discovered during reclamation of the well pad and appears to be the result of daily operations at the well site.

Describe Area Affected and Cleanup Action Taken.\*

Release site will be remediated to NMOCD Artesia District Office requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	John J. Pulte			Approved:  District Supervisor	
Title:	Operations Engineer			Approval Date:	1-8-10
E-mail Address:	jpulte@fairwayresources.com			Expiration Date:	1-8-10
Date:	2/25/10			Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	817-416-1946				

\* Attach Additional Sheets If Necessary

