


District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name Lily ALY Federal #1 Battery	API Number 30-015-27262	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-80645
--------------------------	--------------------------	-----------------------

#### LOCATION OF RELEASE

Unit Letter A	Section 3	Township 24S	Range 31E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.25173 Longitude 104.75878

#### NATURE OF RELEASE

Type of Release Oil	Volume of Release 11 B/O	Volume Recovered 7 B/O
Source of Release Production tank	Date and Hour of Occurrence 12/8/2009, AM	Date and Hour of Discovery 12/8/2009, AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Diversion line from lact unit unloaded to full stock tank with pressure causing it to release from thief hatch. Vacuum truck called, crews called to move line and clean up location.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 50' X 20'. Vacuum truck recovered remaining oil. Will conduct vertical & horizontal delineation to determine extent of contamination. Work plan to be submitted. <b>Depth to Ground Water: &gt;100' (approx. 160', Section 2, T24S-R31E, per New Mexico Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: &gt;1000', SITE RANKING IS 0. Based on impacted soils excavated, sample results and site ranking, Yates Petroleum Corporation requests closure.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: <u>4-8-10</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleun.com	Conditions of Approval: <u>N/A</u>	Attached <input type="checkbox"/> <u>N/A</u>
Date: Wednesday, April 07, 2010 Phone: 575-748-4217	2RP-373	

\* Attach Additional Sheets If Necessary

2RP: 373