District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rto Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003
omit 2 Copies to appropriate

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-10087 **Release Notification and Corrective Action** NSEB 08266 50355 **OPERATOR** Initial Report Final Report Name of Company: Arena Resources, Inc. 210420 Contact: Fred Holmes Telephone No.: 575-738-1739/432-563-2200 Address: 2130 W. Bender Blvd. Facility Name: North Benson Queen Well #16 Facility Type: Produced Water Injection Surface Owner: BLM Mineral Owner: BLM Lease No.: 33129 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County 30E 28 188 1650 FSI. FFI. J 1651 Eddy Latitude: N32 42' 56.300" Longitude: W103 58' 26.600" NATURE OF RELEASE Type of Release: Produced Water & Oil Volume of Release: 125 Volume Recovered: 50 Source of Release: Injection Line Break Date and Hour of Occurrence: Date and Hour of Discovery: 07/29/08 0700 07/29/08 0900 Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☒ No ☐ Not Required Sherry Bonham, OCD/ James Amos, BLM By Whom? Tony Tucker - Foreman Date and Hour 07/29/08-1000 If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.*: Describe Cause of Problem and Remedial Action Taken.*: Break in a 2" produced water line. Line was repaired. Describe Area Affected and Cleanup Action Taken.*: Affected areas include 2 pooled areas of produced water west and north of the wellhead as well as stormwater drainge channels spill used to reach pooled area. Soils were excavated and processed via soil washing to remove chlorides to acceptable levels per corrective action plan. Once soils were treated, they were placed back into the excavation the areas contoured and seeded as per the corrective action plan and BLM requirements. Final report prepared on 06/30/2009 and presented to OCD Artesia on 07/10/09. Closure was approved. Site will move to monitoring for the next two years per BLM requirements to ensure that reclaimed areas properly vegetate. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by District Supervisor: Printed Name: Fred Holmes Title: Consultant Approval Date: 8-2609 **Expiration Date:**

Conditions of Approval:

Attachee

2RP- 22

Attach Additional Sheets If Necessary

E-mail Address: fred@etechenv.com

A 50B08266 51518

Date: 07/10/09

VIO#SEB082665125# -closed

Phone: 432-563-2200