

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 8 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-31283

Release Notification and Corrective Action

255333

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Lime Rock Resources Operating Company	Contact Jerry Smith (Operations foreman)
Address 303 East Main Street, Artesia, N.M. 88210	Telephone No. 575-748-9724
Facility Name Resler State P.W. Transfer pump	Facility Type Water line

Surface Owner State	Mineral Owner State	Lease No.
---------------------	---------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	25	17s	27e	330'	FSL	990'	FEL	EDDY

Latitude 32.79886 Longitude 104.22687

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 80 bbls	Volume Recovered 1 bbl
Source of Release Water Transfer line	Date and Hour of Occurrence 04/26/2010 7:00am	Date and Hour of Discovery 04/26/2010 7:00am
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? NMOCD/Sherry Bonham	
By Whom? Michael Barrett	Date and Hour 04/26/2010 2:00pm	
Was a Watercourse Reached? ☐ Yes ☐ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

The flow path for the release did extend into a drainage area that's leads ultimately to Logan's Draw.

Describe Cause of Problem and Remedial Action Taken.*

The poly flow line used to transfer produced water ruptured. The line was taken out of service and repaired. A vacuum truck was immediately brought to the site, free waters were recovered, and recovered water was disposed at an appropriate disposal facility. An emergency one call was made on 04/27/2010 to the New Mexico One Call. Berms were then constructed upgrade of the drainage area to prevent the run off of any rain that might occur. On April 28, 2010 the excavation of the impacted soil began.

Describe Area Affected and Cleanup Action Taken.*

The release occurred near the lease road south of the Resler State #1. The release area was measured to be 50 yds x 40 yds. Produced waters flowed downgrade to a road used to maintain an anode bed, the release followed the maintance road for 100 yds in a narrow flow path est. to be 2' in width. The release entered into a drainage area and then flowed north; the impacted area located in the drainage area was measured to be 70 yds long x 7 yds wide. The impacted soil has been excavated an transported to Lea Land LLC. A total of 1,838 cu. yds of impacted soil was transported to Lea Land LLC. A 20 Mil. Liner was placed into the main excavated area, the excavated area was then backed filled too surface using clean soil. Remediation actions have been completed as per the Work plan submitted to NMOCD on May 13, 2010. Lime Rock Resources requested closure for the release that occurred on April 26, 2010 at the Resler State P.W. transfer pump. Final analytical results are attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by: 	
Title: Production Supervisor	Approval Date: AUG 02 2010	Expiration Date:
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:	Attached ☐
Date: 7-8-10	Phone: 575-623-8424	

* Attach Additional Sheets If Necessary

n SEB10125-49380
p MCB10147 28256

2RP-414