

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-32554

Release Notification and Corrective Action

NMLB1029539506

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Lime Rock Resources	Contact Michael Barrett
Address P.O. Box 2147 Roswell, NM 88202-2147	Telephone No. 575-623-8424
Facility Name Williams A Federal Battery	Facility Type Production Battery

Surface Owner	Mineral Owner Federal	Lease No. NM 04834
---------------	-----------------------	--------------------

LOCATION OF RELEASE

Unit Letter N	Section 29	Township 17s	Range 28e	Feet from the 590'	North/South Line FSL	Feet from the 2185'	East/West Line FWL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 85 bbls	Volume Recovered 0
Source of Release	Date and Hour of Occurrence 08/02/2010	Date and Hour of Discovery 08/02/2010 8:30am
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notified Mike Bratcher by voicemail.	
By Whom? Michael Barrett	Date and Hour 08/03/2010 8:25am	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

3" poly line split, releasing 85 bbls of water. Isolated, emptied & removed line from service.

Describe Area Affected and Cleanup Action Taken.\*

Approximately affected surface; 50' x 155'. Packed and rocky dry caliche. Notified BLM. Remediation actions were taken by Talon/LPE. Attached Remediation Work plan and Closure report dated October 7, 2010.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Barrett</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Michael Barrett</i>	Approved By <i>Mike Bratcher</i> Signed By District Supervisor	
Title: <i>Production Supervisor</i>	Approval Date: <b>OCT 22 2010</b>	Expiration Date: <i>N/A</i>
E-mail Address: <i>mbarrett@limerockresources.com</i>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <i>Oct-14, 2010</i>	Phone: <i>575-623-8424</i>	

\* Attach Additional Sheets If Necessary

RECEIVED

OCT 15 2010

NMOCD ARTESIA

2RP-448