

RECEIVED JAN 15 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLC/030133118 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	Skelly Unit 967	Facility Type	Battery



Surface Owner	Federal	Mineral Owner		Lease No.	NMLC029420A/ 30-15-35871
---------------	---------	---------------	--	-----------	--------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	31E	1250	South	990	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release- Oil & water	Volume of Release-15 bbls	Volume Recovered- 10
Source of Release- 1" nipple on pumping tee	Date and Hour of Occurrence- 12/31/09	Date and Hour of Discovery 12/31/09
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* There was a hole in the 1" nipple on the pumping tee.		
Describe Area Affected and Cleanup Action Taken.* The majority of the fluid remained on the pad. A little of the fluid ran off the west side of the pad covering a 10' x20' area of the pasture. We will scrape the pad and haul off contaminated soil and wait on approval to clean the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo	Signed By  Approved by District Supervisor:	
Title: Regulatory Analyst	Approval Date: OCT 28 2010	Expiration Date:
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: <i>Remediation per NMOCD Rules & Guidelines</i>	Attached <input type="checkbox"/>
Date: 01/13/10	Phone: 432-685-4332	

* Attach Additional Sheets If Necessary

Remediation plan approved

2 RP-451