District J 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resource

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

SEP 1 6 2010

Form C-141 Revised October 10, 2003

NMOCD ARTESIAC Office in accordance with Rule 116 on back side of form

30-015-34538

Release Notification and Corrective Action

MYB/03083	5699					OPERA	ΓOR	🛛 Initi	al Report	☐ Final Report	
Name of Com		COG OP	ERATIN	G LLC 229/37	, [Contact	Pa	at Ellis		•	
				dland, TX 79701		Telephone No. 432-230-0077					
Facility Name	<u> </u>	Mesilla Stat	e #3 Tanl	k Battery		Facility Type Tank Battery					
Surface Owner State Mineral Owne						r Lease No. B-2103					
3011400 0 11110	, Other		·····					Beaso :	10. 22.03		
				,,,,,,,		OF RE			,		
Unit Letter S	Section 16	Township 17S	Range 30E	Feet from the	North/	South Line	Feet from the	East/West Line	County E	ddy	
				Latitude 32 5		-	ide 103 58.155				
				NAT	URE	OF REL					
Type of Release Source of Release	e BS &		······································			Volume of Release 60bbls Volume Recovered 50bbls Date and Hour of Occurrence Date and Hour of Discovery					
Source of Relea	ase PVC	water leg							Date and Hour of Discovery 09/03/2010 8:30 a.m.		
Was Immediate	Notice G	iven?				If YES, To		, 07/03/20		·	
		\boxtimes	Yes [No Not Rec	quired	d Mike Bratcher—OCD					
By Whom? Josh Russo						Date and Hour 09/03/2010 8:30 a.m.					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
			Yes 🗵] No							
If a Watercours	e was Imp	oacted, Descr	ibe Fully.'	*		·					
•											
Describe Cause	of Proble	m and Dama	dial Actio	n Tolvan *							
Describe Cause	of Proofe	in and Keine	aiai Actio	ii rakcii.							
High wind spee	ed moved	the supports I	oracing the	PVC water leg an	d broke	e it in half car	using the release.	The PVC water le	g has been re	placed with a new	
steel water leg.											
Describe Area	A fracted o	and Cleanup /	Action Tal	·an #							
Describe Area A	Allected a	ind Cicarap r	sciini tar	CII.							
Initially we rele	ased 60bl	ols of BS&W	from the	broken water leg a	nd we v	vere able to r	ecover 50bbls wit	h a vacuum truck.	The spill area	covered a portion	
				200' from the batt							
				has been hauled to the tank battery, (A							
				ent a remediation v							
			•								
I hereby certify	that the in	nformation gi	ven above	is true and comple	ete to th	ne best of my	knowledge and u	nderstand that pur	suant to NMC	CD rules and	
				nd/or file certain re se of a C-141 repor							
				investigate and re							
or the environm	ient. In ac	Idition, NMC	CD accep	tance of a C-141 r							
federal, state, or	r local law	/s and/or regu	lations.					-			
		—					OIL CONS	SERVATION	DIVISIO	<u>N</u>	
Signature:		1	/-					n 1 1 1			
						Approved by	Distigned By	MI/4 DES	much	-	
Printed Name:		Josh	Russo								
Title		Her C	aardinate-			Annewal Da	NOV 0 4	ZUM	Data		
Title:		rioe C(oordinator			Approval Dat	С.	Expiration	ілис:		
E-mail Address:		jrusso@conc	horesoure	es.com		Conditions of	Approval:		A 44. 1 1		
							ATION per OC	D Rules and	Attached	Ц	
Date: 09/15/20		Pho		32-212-2399		REMEDIA	CLIDALT DEAL	IEDIATION			
Attach Additio	onal Shee	ts If Necess	ary		G	iuidelines.	SUBMIT REM	1	-1	QD 1/2	
					P	ROPOSAL	BY: 12/4/	2010	α	11-42	
					-		10-111		- /	, ,	