

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 16 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-20972

Release Notification and Corrective Action

NMLB103204652

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Northwest Central Tank Battery	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No.	NMNM-86025
---------------	---------	---------------	--	-----------	------------

McIntyre DK Fed #6

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E	990	South	2310	West	Eddy

Latitude 32 49.813 Longitude 103 59.725

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	6bbls
Source of Release	Drip tank	Date and Hour of Occurrence	11/04/2010	Date and Hour of Discovery	11/04/2010 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The dump was stuck on a scrubber causing fluid to travel down the gas line to the second scrubber which then transferred into the drip tank causing the overflow. The dump has been repaired.

Describe Area Affected and Cleanup Action Taken.*

Initially 15bbls was released from the drip tank and we were able to recover 6bbls with a vacuum truck. The dimensions of the spill area are as follows: 15' x 15' area in front of the of the drip tank, 1' trail from drip tank across pad leading to 15' x 20' area near cattle guard. (The closest well location to the release is on the same pad as the Tank Battery, McIntyre DK Federal #6, API# 30-015-20972). Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Russo	Approved by District Supervisor: 	
Title: HSE Coordinator	Approval Date: NOV 16 2010	Expiration Date:
E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/16/2010 Phone: 432-212-2399	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 12/16/2010	

* Attach Additional Sheets If Necessary

2RP-479