<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

NOV 22 2010

RECEIVED

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Submit 2 Copies to appropriate

NMOCD ARTESIA with Rule 116 on back side of form

	. • 1.5 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	,	•	Sa	anta Fo	e, NM 8/3	005					0.00
Release Notification and Corrective Action												
MLBO	91344	1726			OPERATOR						Final Report	
Name of Company Marks & Garner Production LTD Co.						OPERATOR         ☐ Initial Report         ☑ Final Report           Contact         Quinton Welborn						
Address	P.O. Box	x 1089, Hobb		Telephone No. (575) 393-9358								
Facility Nar	ne Cave	State #4				Facility Type Oil Well						
Surface Owner: State of NM Mineral Owner						r: Marks & Garner API No. 30-015-24742 2RP # 307						
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the East		Vest Line	County		
F	4	178	29E	1650	1	North	1650 V		est est	Eddy		
	L	<u> </u>	<u> </u>	<u> </u>				<u> </u>		L		
Latitude_N 32.86636° Longitude_W 104.08299°												
NATURE OF RELEASE												
Type of Rele	ase (	Oil and Water			Volume of Release Unknown Volume Recovered None						;	
Source of Release Well head						Date and Hour of Occurrence Date and Hour of Discovery						
Was Issandi	ta Matina (	Cinama		Unknown Unknown If YES, To Whom?								
Was Immedia	ate Notice (		Yes 🛭	No Not Ro	equired	II 1E5, 10	wnom?					
By Whom?					Date and Hour							
Was a Water	course Read	ched?	No		If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
Describe Cau Leak at Well			dial Action	n Taken.*								
		and Cleanup A	Action Tak	en.*								
An area approximately 45' x 55' was excavated to a depth of 8' bgs, lined with 20 mil plastic and backfilled with clean caliche per OCD guidelines. A Remediation Report with complete details is attached.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations al	loperators	are required to	o report an	nd/or file certain r	elease ne	otifications as	nd perform correc	tive acti	ons for rela	eases which	may en	danger
				e of a C-141 repo								
				investigate and retance of a C-141								
		ws and/or regu		tance of a C-141	report de	oes not renev	e the operator of i	esponsi	onity for Co	omphance w	iui any	ouici
,							OIL CONS	SERV	ATION	DIVISIO	N	
•	)	ء مربا			4.							
Signature: 0	remo	in Was					a I !	i il			ļ	
Printed Name	: Quinton	ı Welborn		1	Approved by	Distrigrate Stu Barvis	34.11/4	DKNO	ucor_	-		
		···				DEC U3 2	(n)Va		.1			
Title: Manager						Approval Dat	e: 20 2	שיש E	xpiration l	Date: N/4		
E-mail Addre	ss: awelh	orn@valornet	.com		1	Conditions of	Approval: NA		)		_	
								. 1	/	Attached		

<sup>10/13/10</sup> Phone: (575) 393-9358 Date: \* Attach Additional Sheets If Necessary