

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Marathon AGI State #2-H	API Number 3001534144	Facility Type Battery
Surface Owner State	Mineral Owner State	Lease No. V-2480

LOCATION OF RELEASE

Unit Letter D	Section 33	Township 17S	Range 24E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.79729 Longitude 104.59979

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 14 B/PW	Volume Recovered 0 B/PW
Source of Release Production tank	Date and Hour of Occurrence 1/18/2011, AM	Date and Hour of Discovery 1/18/2011, AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Hole in side of production tank. Called vacuum truck and roustabout crew.		

RECEIVED

JAN 24 2011

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 10' X 10', produced water collected in depression of removed tank (battery had two tanks, but one removed where PW collected). No produced water was recovered. Current production tank repaired (hole plugged/tank recoated). Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OGD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OGD. **Depth to Ground Water: >100' (approx. 290', Section 26, T17S-R24E, per New Mexico Office of the State Engineer and 225', per the Chevron/Texaco trend map). Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Robert Asher

Title: Environmental Regulatory Agent

E-mail Address: boba@yatespetroleum.com

Date: Monday, January 24, 2011

Phone: 575-748-4217

Approved by District Supervisor: 

Approval Date: 2/17/2011

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
3/17/2011

2 RP-582

* Attach Additional Sheets If Necessary