<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
District IV
District IV
District IV
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

MUB1022134929

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

RECEIVED	Form C-141 ised October 10, 2003
NOV 05 28119mit 2 C	opies to appropriate Office in accordance
NMOCD ARTESIA	

Initial Report

Final Report

1220 South St. Francis Dr. Santa Fe, NM 87505 Release Notification and Corrective Action

OPERATOR

Name of Company OGRID Number								Contact						
Yates Petroleum Corporation 25575							Amanda Trujillo							
Address						1	Telephone No.							
104 S. 4 TH Street							575-748-1471							
Facility Nat					I Number		Facility Type Order Number							
Federal CW-B #4 30-015-23200 Oil w								Dil well 2RP- 425						
Surface Ow	ner				Mineral C)wner						Lease 1	No.	
Federal	1161			1	Federal	WIICI						NM-439491		
rederal rederal											NWI-439491			
LOCATION OF RELEASE														
Unit Letter	Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
L	1	19S	24E	i .	1650	ı	South 990 West Eddy							
Latitude <u>N33.13240</u> Longitude <u>W104 13323</u> NATURE OF RELEASE														
,									Volume of Release Volume Recovered					
oil							- 1	unknown			İ	0		
Source of Re	lease							Date and I-	lour of	Occurrence	e	Date and Hour of Discovery		
Flowline								unknown				04/26/20	10 - PM	
								If YES, To						
		\boxtimes	Yes _	J No	☐ Not Re	equired		Mike Brate	cher – N	NMOCD/A	rtesia			
By Whom?								Date and F						
Amanda Truj			orporation				04/26/2010 pm							
Was a Water	course Reach	ned?	5				If YES, Volume Impacting the Watercourse.							
10 137	T			No				N/A						
If a Watercou N/A	irse was imp	acted, Descri	be Fully.*											
	se of Problem	m and Remed	lial Action	a Taker	n *									
Describe Cause of Problem and Remedial Action Taken.* Flow line developed a leak. Once discovered the well was shut in. Necessary repairs were made. Contaminated soil was excavated and hauled to														
appropriate facility.														
Describe Area Affected and Cleanup Action Taken.*														
An approxim	ate size of 30)' x 30' was i	mpacted.	The in									e. Soil from the pooling areas	
													ctly into waiting trucks.	
													d material has been removed.	
Depth to Gro Water Body:													rea: No; Distance to Surface	
													suant to NMOCD rules and	
													eases which may endanger	
													eve the operator of liability	
													, surface water, human health	
				tance o	of a C-141 r	eport de	oes	s not reliev	e the op	perator of i	esponsib	ility for co	ompliance with any other	
federal, state,	or local laws	and/or regu	lations.								XED II	. COLONI	DHIMOLONI	
11						OIL CONSERVATION DIVISION								
Signature: Tuillo									A					
3.g		Jagar					1 n	proved by	District	Suparvid	או אא נה	<i> </i>		
Printed Name: Amanda Trujillo								Approved by District Supervisor 1/4 Semuse						
Title: Environ	mental Scier	ntist					Approval Date: 3//5/2011 Expiration Date: MA							
E mail A 11	ans at	Sunta 1				.	<u> </u>		' A · ·	۔ ح <i>مد ألا مد</i> يادين				
E-mail Address: atrujillo@yatespetroleum.com							0	nditions of	Approv	val:	_ • /	$\langle \cdot \rangle$	Attached	
Date: Thursda	ıv Novembe	r 04 2010	Ph	nne: 57	75-748-431 0	0					Final			
Attach Additional Sheets If Necessary $2RP-425$														
											1	グノル		