

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-23078

Release Notification and Corrective Action

AKMW1104136620

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	OXY USA	Contact	Kelton Beaird
Address	1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O)	575-628-4100
Facility Name	DWU Federal # 1	Facility Type	Oil Well with Battery

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	34	19S	28E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Prod. Water / Crude Oil	Volume of Release	301 bbls	Volume Recovered	65 bbls
Source of Release	Nipple from the bottom of the tank	Date and Hour of Occurrence		Date and Hour of Discovery	1-8-11 @ 12:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Kelton Beaird-Oxy	Date and Hour	See above		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

FEB 07 2011

Describe Cause of Problem and Remedial Action Taken.*

Nipple coming off of the Tank battery formed a leak. The well was shut in, tank taken out of service and emptied. A vac truck was called to pick up the remaining fluid left on the ground.

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

Area affected was inside the dikes around the tanks and approx. 60 ft. into the pasture. The affected area will be delineated, and a clean-up plan will be submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton_beaird@oxy.com

Date: 1-12-11

Approved by District Supervisor

Approval Date: 3/9/11

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

Attached ☐

* Attach Additional Sheets If Necessary

2 RP-600

4/9/11