

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 22 2009

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-36461

AKMW 1109729911

OPERATOR

☐ Initial Report ☐ Final Report

| | |
|---|--------------------------------------|
| Name of Company Devon Energy | Contact Shannon Moss, Foreman |
| Address 6488 Seven Rivers Hwy - P.O. Box 250 | Telephone No. 575-748-5232 |
| Facility Name Laguna Salado Battery | Facility Type Gas |

| | | |
|---------------|---------------|-----------|
| Surface Owner | Mineral Owner | Lease No. |
|---------------|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|----------------------|-----------------------|--------------------|---------------|------------------|---------------|----------------|-----------------------|
| Unit Letter | Section 22 | Township 23 | Range 29 | Feet from the | North/South Line | Feet from the | East/West Line | County Eddy |
|-------------|----------------------|-----------------------|--------------------|---------------|------------------|---------------|----------------|-----------------------|

Latitude **N 32.299221** Longitude **W 103.97480**

NATURE OF RELEASE

| | | |
|---|---|--|
| Type of Release Produced Water | Volume of Release 30 bbls | Volume Recovered 0 |
| Source of Release 4" poly SWD line, extending from the Laguna Salado Battery to the Remuda Basin SWD, ruptured; releasing approximately 30 bbls of produced water. | Date and Hour of Occurrence 09/15/09 - 9:30 | Date and Hour of Discovery 09-15-09 - 9:30 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Paul Evans - BLM OCD | |
| By Whom? Shannon Moss, Foreman | Date and Hour 9:45 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* At the Laguna Salado Battery, a road grader clipped a 4" poly SWD line, extending from the Laguna Salado Battery to the Remuda Basin SWD, thus causing it to rupture; releasing approximately 30 bbls of produced water. | | |
| Describe Area Affected and Cleanup Action Taken.* 50' x 50' Sandy Pasture - Valves closed and area bermed, Leak repaired and contaminated soil removed and hauled to disposal site. | | |

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|------------------------------|
| Signature: Mykol Horner | OIL CONSERVATION DIVISION | |
| Printed Name: Mykol Horner | Approved by District Supervisor: | |
| Title: Field Tech 1 | Signed By: <i>[Signature]</i> | Approval Date: 4/7/11 |
| E-mail Address: mykol.horner@dvn.com | Expiration Date: | Conditions of Approval: |
| Date: 09/18/09 Phone: 575-748-0160 | Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: | |
| Attached <input type="checkbox"/> | | |

* Attach Additional Sheets If Necessary

PROPOSAL NOT LATER THAN:

5/7/11