

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

12/10/10 1109232985 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company OXY USA <i>192463</i>	Contact Kelton Beaird
Address 1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O) 575-628-4100
Facility Name US FED 13-2	Facility Type Gas Well

Surface Owner BLM	Mineral Owner BLM	Lease No. API # 3001534272
-------------------	-------------------	----------------------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	13	22S	24E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1600 bbls.	Volume Recovered 0
Source of Release Steel Flowline	Date and Hour of Occurrence	Date and Hour of Discovery 10-29-10 @ 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (Left Message) Terry Gregston (sent e-mail)	
By Whom? Kelton Beaird (HES Oxy)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
Steel Flowline Corroded causing the leak. The leak was isolated and the line was repaired

Describe Area Affected and Cleanup Action Taken.*
Area affected was off the lease road apprx. 400 yards in the pasture. A sample of the water was taken and the chloride concentration is 1620 ppm. Due to impenetrable rock, Oxy will monitor this area for re-growth and submit pictures in the summer of 2011.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION Accepted for record NMOCD	
Printed Name: Kelton Beaird	Approved by District Supervisor:	
Title: HES Specialist	Approval Date:	Expiration Date:
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-4-10		

* Attach Additional Sheets If Necessary