<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

MAR 1 8 2011 Revised October 10, 2003

NMOCD AR III 2 Copies to appropriate SIAO frice in accordance with Rule 116 on back side of form

NHMW 110157946 Release Notification and Corrective Action OPERATOR Initial Report Final Report								
Name of Company OGRID Numb	ber	Contact						
Yates Petroleum Corporation 25575 Address		Amanda Trujillo						
			Telephone No. 575-748-1471					
Facility Name API Number	Facility Type Order Number							
Koonunga Hill BGX Federal #1 30-015-34380	i			Gas well 2RP- 735				
Surface Owner Mineral Ov	Mineral Owner			Lease No.				
Federal Federal	NM - 103							
LOCATION OF RELEASE								
	/South Line Feet from the East/West Line County							
E 19 22S 25E 1838	<u> </u>	NORTH 1072			EST	EDDÝ		
NATURE OF RELEASE								
Type of Release WATER Produced Water Source of Release Date and Hour								
WATER Procluced Water	75			70				
Source of Release 4" Check Valve froze and broke during the thaw out process.	Date and H 2/10/2011				Date and Hour of Discovery 2/10/2011 - AM			
			If YES, To Whom?					
1			Mike Bratcher – NMOCD/Artesia					
By Whom?	Date and Hour							
Amanda Trujillo - Yates Petroleum Corporation Was a Watercourse Reached?	02/11/2011 am If YES, Volume Impacting the Watercourse.							
Was a Watercourse Reached? ☐ Yes ☒ No			N/A					
If a Watercourse was Impacted, Describe Fully.* N/A								
Describe Cause of Problem and Remedial Action Taken.* Discharge waterline froze, causing a release of produced water. Release was held inside lined berm. Vacuum truck was dispatched to pick up standing fluids.								
Describe Area Affected and Cleanup Action Taken.*								
An approximate size of 20' x 20' was impacted. Release was held inside lined berm. Vacuum truck was dispatched to pick up standing fluids.								
Contaminated gravel was removed and replaced. Depth to Ground Water: >50' (approx. 65', per New Mexico State Engineers office); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 10. Based on site ground water quality and enclosed								
analytical results.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
regulations all operators are required to report and/or tile certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health								
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other								
federal, state, or local laws and/or regulations.								
OIL CONSERVATION DIVISION Accepted for rec								
Signature 120	NMOCD / /							
Printed Name: Amanda Trujillo	4	Approved by District Supervisor:				+/11/z cil		
Title: Environmental Scientist	-	Approval Date		Es	epiration I	Date:		
	Π,	Conditions of Approval; See Cana			:1			
E-mail Address: atrujillo@yatespetroleum.com		Conditions of .	onunions of Approvat See Cina		'	Attached -		
Date: Wednesday, March 16, 2011 Phone: 575-748-4310					***************************************			
* Attach Additional Sheets If Necessary								

No analytical or water quality data was included with this submittal

Release 2 of 2

Bratcher, Mike, EMNRD

From:

Bratcher, Mike, EMNRD

Sent:

Thursday, March 17, 2011 3:52 PM

To: Subject: 'Amanda Truiillo'

RE: C-141 submittals

Amanda,

I can work with this, but I have some questions.

On the Koonunga Hills Pipeline release, this is probably a cut & paste or template error, but on the C-141, under Cause, you have listed that the release was held inside a lined berm. As I understand from the rest of the information, this was a cumulative 75 bbl release coming from 22 release points over a 7 mile stretch of pipeline. Please resubmit a corrected copy.

Where does this line begin and terminate?

Has BLM requested Yates to provide notification of releases on Fed properties?

When submitting C-141s, you have listed after the site ranking, "Based on site ground water quality and enclosed analytical results." Could you explain what you are referring to with this statement?

With the two releases on the Koonunga Hill BGX Fed #1 site, there was 5 bbls unaccounted for with each release. The C-141 for the 2/10/11 release indicates the gravel was replaced. Was the liner integrity checked? If it was, please send an addendum to the C-141 stating the condition of the liner and what the suspected or known 10 bbl loss of fluid would be attributed to.

Thanks,

MIKE BRATCHER

NMOCD District 2 1301 W. Grand Ave. Artesia, NM 88210 575-748-1283 Ext.108 575-626-0857 mike.bratcher@state.nm.us AS OF 411/2011 NO RESPONSE

HAS BEEN RECIEVED

From: Amanda Trujillo [mailto:atrujillo@yatespetroleum.com]

Sent: Wednesday, March 16, 2011 4:02 PM

To: Bratcher, Mike, EMNRD Subject: RE: C-141 submittals

Mike:

Attached are the C-141s plus a few more. Would you rather have me send these in separate emails for your documentation supposes?

OhKay SWD #3 Release date 2/17/11

- Konnunga Hills BGX Fed #1 Release dates (2 releases) 2/7/11 and 2/10/11
 - 1. I am requesting closure on the Koonunga Hill spills. Attached are two Initial/Final C-141s. Both releases occurred in a lined berm
 - 2. There are is an additional C-141 for the pipeline
- Saguaro AGS #4 Reported 2/7/11
- Osprey BPS St #1-H Reported 2/4/11
 - 1. I am requesting closure on the Osprey#1-H spills. Attached are two Initial/Final C-141s. Both releases occurred in a lined berm

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

----Original Message----

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Monday, March 14, 2011 10:28 AM

To: Amanda Trujillo **Subject:** C-141 submittals

Amanda,

I guess this is my day to bug you. I am checking on C-141 Initial Report for the following reported releases:

- OhKay SWD #3 Release date 2/17/11
- Konnunga Hills BGX Fed #1 Release dates (2 releases) 2/7/11 and 2/10/11
- Saguaro AGS #4 Reported 2/7/11
- Osprey BPS St #1-H Reported 2/4/11

Thanks,

Mike Bratcher

NMOCD DISTRICT 2 1301 W. GRAND AVE. ARTESIA, NM 88210 575-748-1283 EXT.108 mike.bratcher@state.nm.us