

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAR 16 2011

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

5 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

*nkmlw 1110228909*

Release Notification and Corrective Action  
OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471	
Facility Name OhKay SWD #3	API Number <i>30-015-35164</i> <del>30-015-05509</del>	Order Number 2RP- <i>737</i>
Surface Owner State	Mineral Owner State	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	6	25S	30E	990	SOUTH	2310	East	EDDY

Latitude N33.13240 Longitude W104.13323

NATURE OF RELEASE

Type of Release WATER <i>Produced Water</i>	Volume of Release 60	Volume Recovered 10
Source of Release Tanks ran over while battery was down due to failure to shut in a necessary line	Date and Hour of Occurrence 2/17/2011	Date and Hour of Discovery 2/17/2011 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 02/23/2011 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Tanks ran over while battery was down due to failure to shut in a necessary line. Water flowed into berm. Broken drain line caused fluid to escape berm. Valves were shut off and a clean up crew was dispatched to make necessary repairs and remedial steps.		
Describe Area Affected and Cleanup Action Taken.* An approximate size of 60' x 6' was impacted. The impacted area is located on the north end of the battery. Soil from the pooling areas was excavated and disposed of at an NMOCD approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water: >100' (approx. 250', per New Mexico ChevronTexaco Trend Map); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. <i>Based on site ground water quality and enclosed analytical results.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>A Trujillo</i>	Approved by District Supervisor <i>Signed By Mike Bratcher</i>	
Printed Name: Amanda Trujillo	Approval Date: <i>4/11/2011</i>	Expiration Date:
Title: Environmental Scientist	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: atrujillo@yatespetroleum.com	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>5/11/2011</i>	
Date: Tuesday, March 15, 2011 Phone: 575-748-4310		

\* Attach Additional Sheets If Necessary

☒ No analytical or water quality data was included with this submittal

## Bratcher, Mike, EMNRD

---

**From:** Amanda Trujillo [atrujillo@yatespetroleum.com]  
**Sent:** Wednesday, February 23, 2011 5:30 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Jerry Fanning  
**Subject:** OhKay SWD #3

Mr. Bratcher:

Yates Petroleum reports a release at the following location:

Ohkay SWD #3  
Section 6, Township 25 South, Range 30 East  
Eddy County  
Date of Release: 02-17-2011  
Approximately 60 barrels of water were released 10 barrels recovered  
Cause of release has been isolated and repairs were completed  
Vacuum truck on site recovered standing fluids  
Site will be evaluated and a work plan for remediation will be submitted for consideration.

Please excuse the tardiness with this report there was a mix up with field personnel and the copy of the report. If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo  
Environmental Scientist  
Yates Petroleum Corporation  
Office 575-748-4310  
Cell 575-703-6537  
Email [atrujillo@yatespetroleum.com](mailto:atrujillo@yatespetroleum.com)