

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nkmw 1111656409

Name of Company OXY USA <i>192463</i>		Contact Kelton Beaird
Address 1502 W. Commerce Carlsbad, NM 88220		Telephone No. (O) 575-628-4100
Facility Name Jones Canyon 4-5		Facility Type Gas Well

OPERATOR

☒ Initial Report ☐ Final Report

Surface Owner Federal	Mineral Owner	Lease No. <i>APL 30015 30933</i>
-----------------------	---------------	----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	4	22S	24E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50bbls	Volume Recovered 2
Source of Release Check Valve	Date and Hour of Occurrence <i>4-6-11 @ 10:30am</i>	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD, Terry Gregston - BLM	
By Whom? Kelton Beaird - Oxy	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Check valve busted. Well was shut-in; vacuum truck was called

RECEIVED

APR 21 2011

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

Fluid ran from the vessel south through the location and into the pasture apprx. 1000ft. Area on the location will be delineated as practicable due to hard rock. Area in pasture is solid rock, therefore delineation will not be possible. A water sample will be pulled, sampled, and submitted with the work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *[Signature]*

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton_beaird@oxy.com

Date: 4-8-11

OIL CONSERVATION DIVISION

Approved by District Supervisor *[Signature]*

Approval Date: *4/26/11*

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

Attached ☐

2 RP-762

5/26/11

* Attach Additional Sheets If Necessary