

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00300 ✓
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other: <u>Water Injection Well</u>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator LIME ROCK RESOURCES II-A, L.P. ✓		6. State Oil & Gas Lease No.
3. Address of Operator c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401		7. Lease Name or Unit Agreement Name ATOKA SAN ANDRES UNIT ✓
4. Well Location Unit Letter: <u>C</u> : <u>990</u> feet from the <u>NORTH</u> line and <u>2310</u> feet from the <u>WEST</u> line ✓ Section <u>11</u> Township <u>18-S</u> Range <u>26-E</u> NMPM <u>Eddy</u> County		8. Well Number <u>#101</u> ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3320' GL		9. OGRID Number <u>277558</u> ✓
		10. Pool name or Wildcat: Atoka, San Andres (03610)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: P&A ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/5/11: MIRUSU. Found pkr stuck. Cut 2-3/8" tbg off @ 1613' & TOH. OCD inspector, Phil Hawkins approved procedure changes. Set CIBP @ 1603'. Circ plugging mud. Spot 75 sx cmt @ 1603'. WOC & tagged @ 950'. Perfed 5-1/2" csg @ 130' & circ 45 sx cmt down 5-1/2" csg & out bradenhead. (Outside of 7-5/8" surface csg had been cemented to surface in the past by a former operator). Cut off wellhead & anchors. Set P&A marker in cmt. Released P&A rig on 5/8/11. Leveled & cleaned up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Pippin TITLE Petroleum Engineer - Agent DATE 5/19/11

Type or print name Mike Pippin E-mail address: mike@pippinllc.com PHONE: 505-327-4573

For State Use Only

APPROVED BY: Phil Hawkins TITLE _____
Conditions of Approval (if any): _____

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms. www.emnrd.state.nm.us/oed.

DATE 5/23/2011

RECEIVED
MAY 20 2011
NMOCD ARTESIA

13