

Land Office **Las Cruces**
061302
Lease No. _____


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

FEB 15 1960

APPROVED



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 4

1959

Federal Chaves
Well No. **2-24** is located **1450** ft. from **SW** line and **1450** ft. from **E** line of sec. **24**
N1/4S1/4 Sec. 24 **138** **27E** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **Chaves** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3605** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate in the logs, cementing points, and all other important proposed work)

This test was plugged as follows:

1. Recovered 143' of 4 1/2" casing, and set 3 5/8" casing
2. Pumped in 3 sack plug 765' - 768'
3. Filled hole with mud.
4. Pumped in 20 sack plug on stub of 4 1/2" casing at 135'.
5. Mudded on top of this plug.
6. Set 2 sack surface plug in top of the 3 5/8" casing and erected the marker pipe.

Work completed 6 P.M., November 3, 1959. Will notify when the cleanup has been made, and location is ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **John H. Trigg**
P. O. Box 5489
Address **Roswell, New Mexico**

By **Hugh W. Peck**
Geologist
Title _____

RECEIVED

NOV 5 - 1959

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

1950
1951
1952

1953
1954
1955

ILLEGIBLE

1432

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTE: ...	SUBSEQUENT REPORTS ...
NOTE: ...	SUBSEQUENT REPORTS ...
NOTE: ...	SUBSEQUENT REPORTS ...
NOTE: ...	SUBSEQUENT REPORTS ...
NOTE: ...	SUBSEQUENT REPORTS ...
NOTE: ...	SUBSEQUENT REPORTS ...

Federal Reserve
WELLS 2-26
 1432
 137
 177
 1432
 1432
 1432
 1432

DETAILS OF WORK

This test was plugged as follows:

1. Runnered 141° of 4 1/2" casing, and at 2 1/2" casing
2. Pumped in 1 sack plus 765° - 785°
3. Rotted hole with sand.
4. Pumped in 28 sack plug on each of 4 1/2" casing at 135°.
5. Rotted on top of this plug.
6. Set 2 sack surface plug in top of the 3 1/2" casing and crossed the water pipe.

Work completed 6 P.M., November 3, 1931. Well ready when the electric log was made, and location is ready for inspection.

Company **John E. Frigg**
 Address **P. O. Box 1489**
Aswell, New Mexico

8
 Title **Geologist**

