

NM OIL CONS COMMISSION

Form 9-331
Dec. 1973

Drawer 730
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

RECEIVED BY UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MAY 07 1985

SUNDRY NOTICES AND REPORTS ON WELLS

NOTE: Use Office Form for proposals to drill or to deepen or plug back to a different record. Use Form 9-331 for such proposals.

1. oil well ☐ gas well ☐ other Dry

2. NAME OF OPERATOR

*Fossils Fuels, Inc. (Jack McClellan - Lessee of record)

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980⁺ FSL & 660' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE

NM-2581

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 11

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Sams Ranch

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11-T14S-R28E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

14. API NO.

30-005-60251

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3589' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
MAY 2 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5/7/82 Plug and Abandoned well as follows:

Set a 25 sack cement plug from 1727'-1800' ← 4 1/2" cut at 577'

Set a 30 sack cement plug from 627'-501'.

Set a 40 sack cement plug from 293'-172'.

Set a 15 sack cement plug at surface and installed dry hole marker.

Heavy mud was placed between each plug.

Location has been cleaned, leveled and ripped and is in process of being restored to its original condition.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark McClellan TITLE Geologist DATE May 28, 1982

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

MAY 3 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

TD 1850

Post ID-2
5-10-85
P+R