

DEPARTMENT OF THE INTERIOR (reverse side)
GEOLOGICAL SURVEY

OR RE

Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 2824

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re-enter or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.

7. WELL TYPE
☐ WATER ☐ GAS ☐ OTHER DRY HOLE

8. NAME OF OPERATOR

McClellan Oil Corporation

9. ADDRESS OF OPERATOR

P. O. Box 848, Roswell, New Mexico 88201

10. FIELD AND POOL, OR WILDCAT
 (See instructions on reverse side and in accordance with any State requirements.)
 (See instructions on reverse side.)

100' FWL & 660' FNL

11. ELEVATIONS (Show whether SP, RT, CA, etc.)

3791.7' CR

12. AGREEMENT NAME

NORTH KING CAMP UNIT

13. FARM OR LEASE NAME

14. WELL NO.

9

15. FIELD AND POOL, OR WILDCAT

WILDCAT

16. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 27-T13S-R29E

17. COUNTY OR PARISH

CHAVES

18. STATE

NEW MEXICO

19. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

20. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

REACHED TOTAL DEPTH OF 1748' ON SEPTEMBER 11, 1973. PURSUANT TO VERBAL INSTRUCTIONS THE WELL WAS PLUGGED AND ABANDONED AS FOLLOWS: 100' CEMENT PLUGS 1748-1648', 910-810' AND 467-367', WITH 10 SX PLUG AT SURFACE. HEAVY MUD WAS PLACED BETWEEN THE PLUGS. THE LOCATION WAS LEVELLED AND CLEANED AND A DRY HOLE MARKER INSTALLED.

RECEIVED

U.S. GEOLOGICAL SURVEY
 WASHINGTON, D.C. 20500

21. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

SECRETARY

DATE

3/27/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side