

COPIES RECEIVED		
TRIBUTION		
FE		
OFFICE		
ATOR		

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-65

SUNDY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.		7. Unit Agreement Name
8. Farm or Lease Name Chatten-Muncy		
9. Well No. 1		10. Field and Pool, or Wildcat Denton Camp (Miss)
11. Field and Pool, or Wildcat Denton Camp (Miss)		
12. County Chaves		13. Elevation (Show whether DF, RT, GR, etc.) 3979-R.T.
14. Elevation (Show whether DF, RT, GR, etc.) 3979-R.T.		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
1. REMEDIAL WORK <input type="checkbox"/> 2. PARTIALLY ABANDON <input type="checkbox"/> 3. OR ALTER CASING <input type="checkbox"/> 4. OTHER <input type="checkbox"/>	5. PLUG AND ABANDON <input type="checkbox"/> 6. CHANGE PLANS <input type="checkbox"/> 7. OTHER <input type="checkbox"/>	8. REMEDIAL WORK <input type="checkbox"/> 9. COMMENCE DRILLING OPNS. <input type="checkbox"/> 10. CASING TEST AND CEMENT JOB <input type="checkbox"/> 11. OTHER <input type="checkbox"/>	12. ALTERING CASING <input type="checkbox"/> 13. PLUG AND ABANDONMENT <input checked="" type="checkbox"/> 14. OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was loaded w/9.5# brine mud. 2100' of 5 1/2" casing was pulled from well.
The following plugs were placed in well:

1. 35 sx 6425 - 6137'
2. 50 sx 2100- - 1900'
3. 65 sx 1510 - 1400'
4. 10 x 15' - back to surface.

No stub plug required.
Dry hole marker 4" x 6" above ground level placed.
Pits, cellar and location filled, leveled and location cleaned of all debris.

Job complete 7-9-77
Recovered 2100' of 5 1/2" casing

* TOP CMT.
5040' TEMP.
SURVEY

* 8 5/8"
70 1460' CIRC.

Patel
172 2
P-A
8-12-77

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

H. D. Oden TITLE President DATE July 27, 1977

APPROVED BY _____ TITLE _____ DATE _____
REMARKS OF APPROVAL, IF ANY:

AC12.1.1.1.1

12.1.1.1.1

12.1.1.1.1