

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
AUG 15 1977

Form C-103
Supersedes Old
C-101 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit / Agreement Name	
8. Farm or Lease Name Chatten-Muncy	
9. Well No. 1	
10. Field and Pool, or Wildcat Denton Camp (Miss)	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	2. Name of Operator H. D. Oden, Inc.
3. Address of Operator P. O. Box 5544, Midland, Texas 79701	4. Location of Well UNIT LETTER 0 , 660 FEET FROM THE south LINE AND 1980 FEET FROM THE east LINE, SECTION 18 TOWNSHIP 6-S RANGE 28-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3979-R.T.	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was loaded w/9.5# brine mud. 2100' of 5½" casing was pulled from well.
The following plugs were placed in well:

1. 35 sx 6425 - 6137'
2. 50 sx 2100- - 1900'
3. 65 sx 1510 - 1400'
4. 10 x 15' - back to surface.

No stub plug required.
Dry hole marker 4" x 6" above ground level placed.
Pits, cellar and location filled, leveled and location cleaned of all debris.

Job complete 7-9-77
Recovered 2100' of 5 ½" casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. D. Oden* TITLE President DATE July 27, 1977

APPROVED BY *Mike C. Thompson* TITLE OIL AND GAS INSPECTOR DATE AUG - 8 1978

CONDITIONS OF APPROVAL, IF ANY: