

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
reverse side)TE*
re-Copy TO SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		MAR 24 1977	
2. NAME OF OPERATOR Yates Petroleum Corporation		O. C. C. ARTESIA, OFFICE	
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL & 330' FEL of Section 31-6S-26E		8. FARM OR LEASE NAME Federal "HJ"	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3668' GR	
		9. WELL NO. 1	
		10. FIELD AND POOL, OR WILDCAT Linda (S. A.)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31-6S-26E Unit A NMPM	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Spud

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 9½" hole at 4:00 PM 3-2-77.

TD 247'. Ran 8 joints of 7" 20# K-55 (244') set at 244' KB. Cemented by Halliburton w/50 sacks of Class C, followed w/100 sacks of Class C 4% CaCl. Circulated 45 sacks to surface. PD 11:15 AM 3-4-77. WOC 18 hours, nipples up, installed pipe rams and tested. OK. Reduced hole to 6¼" drilled plug and tested to 600#. OK. Resumed drilling.

RECEIVED
MAR 21 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine Tomlinson

TITLE

Geol. Secty

DATE

3-19-77

(This space for Federal or State office use)

APPROVED BY

Lee S. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

MAR 23 1977

CONDITIONS OF APPROVAL, IF ANY: