

وللمستقم فيعربن كمسرة مسمو مسروي

.

1

-

ELK OIL COMPANY Dexter State No. 1 Sec. 36-12S-26E Chaves County, New Mexico

Water - 277-284 - 6 bailers per hour Drilled wet hole to 365'. Ran 8-5/8" - 365' - Did not shut off water. Drilled wet hole to 535' & reamed. Lowered 8-5/8" to 505'. Cemented with 50 sx. Exact casing point is questionable? Drilled plug - did not shut off water. Cleaned out caving & drilled to 550'. Again cemented 8-5/8" with 50 sx. Drilled plug and cement. Still had water. Drilled wet to 590'. Ran 7" casing to 588'. Drilled wet hole to 655'. Laid down 20 jts 7" casing. Stuck reamer in hole. Fished. Pulled 13 jts 7". Ran tubing & washed on top of tools. Recovered tools. Reamed & drilled with wet hole & mud to 1000'. Ran 999' 7" casing. Water shut off. Drilled to T.D. of 1188'.

RECEIVED

DEC 3 0 1977

O. C. C.

