

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN PLICATE*
(Other Inst. .008 on re-
verse side)Copy to 17
Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
N M 13986

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED	
2. NAME OF OPERATOR Mountain States Petroleum Corp. ✓		OCT 11 1978	
3. ADDRESS OF OPERATOR P O Box 1936 Roswell, New Mexico 88201		D. C. C. ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660 FNL & 2320 FWL		7. UNIT AGREEMENT NAME	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3565 GR	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		8. FARM OR LEASE NAME Trigg	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *		9. WELL NO. 1 Y	
		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 26T-13S-R27E	
		12. COUNTY OR PARISH Chaves	
		13. STATE NM	

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Subsequent Abandonment

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4/20/78 TD 2240'.

As per verbal approval District Engineer 4/20/78.

Placed 25 sx plug in 4-1/2" open hole, back into 5-1/2" casing.
Recovered 5-1/2" above 1350' (top San Andres). Placed 25 sx
plug in and out of 5-1/2" stub. 25 sx plug across base of 8-5/8" casing.
(313') GR. 10 sx surface plug, with dry hole marker. Heavy mud used
between plug.

RECEIVED
SEP 11 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

KC Haven

TITLE Geologist

DATE 09/13/78

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Jose D. Lara

TITLE ACTING DISTRICT ENGINEER

DATE

OCT 10 1978