		_	6	By LO MIT
Form 9-331 (May 1963) DEPARTMEN: OF THE INTERIOR (Other Instructions re- GEOLOGICAL SURVEY		is re-	i Budget Bureau No. 42-R1424.	
SUNDRY NOTICES AND REPORTS O (Do not use this form for proposals to drill or to deepen or plug ba Use "APPLICATION FOR PERMIT—" for such pro	N WELLS ck that Effected Esserve	¥.ED	6. IF INDIAN, ALLOTTEE	OR TRIBE GAME
1. OIL GAS WELL OTHER Wildcat	JUN - 5		7. UNIT AGREEMENT NAM	E
2. NAME OF OPERATOR		<u></u>	8. FARM OR LEASE NAME	
SUPRON ENERGY CORPORATION	<u> </u>	C.	9. WELL NO.	ral
3. ADDRESS OF OPERATOR SUITE 1700 Campbell Centre 8350 North Central Expressway, Dallas	NODRESS OF OPERATOR Suite 1700 Campbell Centre ACTEDIA, OFFICE 8350 North Central Expressway, Dallas, Texas 75206		1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface			Wildcat Elle burger	
NW/4 SW/4 1980' FSL and 990' FW	Ľ		11. SEC., T., R., M., OR BL SURVEY OR AREA	K, AND
			Sec 8, T-11S, R-27E 12. COUNTY OF PARISH 13. STATE	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF,	RT, GR, etc.)		Chaves	New Mexico
			Chaves	New Mexico
16. Check Appropriate Box To Indicate No	ature of Notice, Rep	port, or O	ther Data	
NOTICE OF INTENTION TO:		SUBSEQUI	ENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	XX	X REPAIRING W	ELL
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATM	ENT	ALTERING CAS	SING
SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACI		ABANDONMEN	
REPAIR WELL CHANGE PLANS	(Norre: Ray)	ort results	of multiple completion o	n Well
(Other) [17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locati nent to this work.) *	durable and also bouth	nont dutop	tion Report and Log form Including estimated date I depths for all markers	of starting any
 Drilled 17-1/2" hole to 320'. Ran 8 jts at 320'. Cemented casing to surface w/31 P.M. on 4/29/78. 	of 13-3/8" 48# 5 sx Class "C"	₩, H-40 Cemen	surface casing t. Plug down @	- set 8:00
2. Drilled out from under surface casing with 24#, K-55 intermediate casing - set @ 154	4'. Cemented	w/750 s	Ran 35 jts of sx cement.	5 8-5/8"
3. Drilled 7-7/8" hole to TD of 6686'. Read	ched TD on 5/26	5/78.	determined to	he pop-
 Ran Dual Laterolog and Compensated Neutro productive, and decision was made to plug The U.S.G.S. office in Artesia was contact 	g and abandon w	while r	ig still on loc	ation.
as follows:	-			
Plug #1 6450 - 6600' w/45 sx.			х -	
Plug #2 6140 - 6290' w/45 sx			•	
Plug #3 5250 - 5400' w/45 sx. Plug #4 2940 - 3080' w/45 sx				· .
Plug #4 2940 - 3080 w/45 SX Plug #5 1500 - 1600' w/45 SX		•		
Plug #6 Surface - 20' w/10 sx Di	ry hole marker	was er	ected.	
6. Location and pit clean-up will be complete	ted upon receip	pt of i	nstructions fro	om the
Bureau of Land Management.				
			· ·	
			• .	
18. I hereby certify that the forceoing is true and correct	Operations Ass:	istant	DATE June	1, 1978
SIGNED				
(This space for Federal or State office use)	•			
APPROVED BY TITLE			DATE	
CONDITIONS OF APPROVAL, IF ANY:	,			

.

*See Instructions on Reverse Side