

UNED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 558973

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

RECEIVED

2. NAME OF OPERATOR

C. E. LaRue and B. N. Muncy, Jr. ✓

DEC 19 1978

3. ADDRESS OF OPERATOR

P.O. Box 196, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

O. G. C.
ARTESIA, OFFICE

1980' FNL & 1980' FEL, Section 17, T14S, R28E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lillie Federal Co.

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Sams Ranch Grayburg

11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA

Section 17, T14S, R28E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3564.5 GL

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Surface casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Ran 243' of 36# Used 10-3/4" casing, circulated with 236 sacks Class C cement w/21

CaCl 12/4/78. Waited 18 hours on cement and tested @ 800# with no leakage.

RECEIVED
DEC 15 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Operator

DATE

12/5/78

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

ACTING DISTRICT ENGINEER

DATE

DEC 18 1978

CONDITIONS OF APPROVAL, IF ANY: