NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor **Betty Rivera** Cabinet Secretary

Lori Wrotenbery Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

02/18/02

H W PACE 3403 Boyd Midland TX 79707-

Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

	P	A	T	ST	ΑT	Έ	00	1
--	---	---	---	----	----	---	----	---

P-30-10S-27E

30-005-60590-00-00

Inspection Date Type Inspection 02/18/2002 Plug / Plug Back

Inspector

*Significant Violation? Non-Compliance?

Corrective **Action Due By:**

Inspection No.

Comments on Inspection:

Gerry Guye

Yes

No

5/13/2002

iGEG0204945175

Well not ready for release - Tank, PVC pipe, catwalk, open pit, fencing and loose pieces of pipe

still on location. Photo

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infra-structure of the oil and gas industry.

Sincerely,

Oil Conservation Division, District II

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.