COPY Form approved, Budget Bureau No. 42-111424. Form 9-331 (May 1963) U.ITED STATES SUBMIT IN TRA. MICATES (Other Instructions on re-DEPARTMENT OF THE INTERIOR (Other in verse side) 5. LEASE DESIGNATION AND SERIAL NO. NM - 36409GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to Rivertely redervoir. Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME JAN 25 198**0** OIL WELL XX WELL OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR McClellan MB Federal Yates Petroleum Corporation C. D. 9. WELL NO. 3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND POOL, OR WILDCAT See also space 17 below.)
At surface Wildcat 1980' FSL & 660' FWL of Section 31-5S-25E Sec. 31-5S-25E Unit L NMPM 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 3855.9' GR Chaves NM Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT SHOOTING OR ACIDIZING ABANDONMENT* ABANDON SHOOT OR ACIDIZE Spud (Other) _ CHANGE PLANS REPAIR WELL

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

(Other)

Spudded a 15" hole at 10:00 AM 1-12-80. Drilled to 360' and ran 9 joints of 10-3/4" 32# H-40 8R, R-3 ST&C casing (362') set at 360'. 1-Texas Pattern guide shoe at 360', insert float at 320'. Cemented w/250 sacks Class "C" 4% CaCl. PD 7:30 PM 1-12-80. Cement circulated 45 sacks WOC 12 hours. Cut off. Reduced hole to 91/2", drilled plug an to surface. tested to 600#. OK. Resumed drilling.

RECEIVED

JAN 24 1980

U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct SIGNED) TITLE	Geol. Secty	DATE 1-24-80
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _		DATIO