

NO. OF COPIES RECEIVED	
DISTRIBUTION	
AMOUNT	
FILE	
S.G.S.	
AND OFFICE	
PERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 25 1980

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLY OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - 1 (FORM C-103) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER: Dry Hole

Name of Operator
Yates Petroleum Corporation

Address of Operator
207 S. 4th St., Artesia, NM 88210

Location of Well
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
East LINE, SECTION 8 TOWNSHIP 10S RANGE 26E NMPM.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
L-4606

7. Unit Agreement Name

8. Farm or Lease Name
Sink Hole "NR" State Com

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat Abo

12. County
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
3800 'GL/3811 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Per instructions obtained on 7/29/80 this well has been plugged as follows:

Cut and recovered 5-1/2" casing from 3325'.
WIH w/tubing and circulated hole w/heavy mud.
Set 1st plug 4085-4185' (20 sx Class C) across perforations 4131-35'.
Set 2nd plug 3275-3375' (60 sx Class C) across 5-1/2" casing stub @3325'.
Waited on cement 2 hours & tagged plug @3261'.
Set 3rd plug 2150-2250' (40 sx Class C).
Set 4th plug 875-1053' (70 sx Class C) across San Andres top @1003' & 8-5/8" casing shoe @926' (no fluid loss in 30 minutes).
Set 5th plug surface - 30'.
Will notify by Sundry Notice when abandonment marker has been installed and location cleaned and leveled.

19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert R. Hall TITLE Engineer DATE 8/21/80

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: