

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED  
NEW MEXICO OIL CONSERVATION COMMISSION

AUG 20 1980

O. C. D.

ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>P &amp; A</b>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Hanagan Petroleum Corporation</b>		5. State Oil & Gas Lease No. <b>L-5029</b>
3. Address of Operator <b>P.O. Box 1737 Roswell, New Mexico 88201</b>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>0</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>27</b> TOWNSHIP <b>4 South</b> RANGE <b>27 East</b> NMPM.		8. Farm or Lease Name <b>Newmill-State</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3969 KB</b>		9. Well No. <b>1</b>
		10. Field and Pool, or Wildcat <b>Wildcat</b>
		12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 6850 granite wash by drillers measurements - Well was plugged & abandoned 7/29/80 (no csg. pulled) in following manner: (Class "H" cmt.) 6738-6838 (35sx), 6500-6600 (35sx), 5940-6040 (35sx), 5300-5400 (35sx), 4550-4650 (35sx), 2500-2600 (35sx), 1300-1400 (35sx), tagged top last plug 1305', 15 sx. plug @ surface w/appropriate dry hole marker w/heavy mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Hugh E. Hanagan TITLE Vice President DATE 8/18/80

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: