الان کې د د ان کې کې کې

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42-R1424	
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE USA - NM 28162	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME RECEIVED	
	8. FARM OR LEASE NAME Thorpe MI Federal OCT 20 1980	
2. NAME OF OPERATOR	9. WELL NO. 2 O. C. D	
Yates Petroleum Corporation V 3. ADDRESS CF OPERATOR	10. FIELD OR WILDCAT NAME	
207 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
below.) AT SURFACE: 1980' FSL & 660' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Unit L - Sec. 3-7S-25E 12. COUNTY OR PARISH 13. STATE Chaves NM	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3812' GR	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF	3812' GR	

c/sF

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertime MEXELS)s, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4150' Ran 100 joints of 5-1/2" 14# K-55 ST&C casing set at 4125'. 1-diff-fill shoe at 4125'. Cemented w/25 sacks 75-25 Poz-fill, 3# KCL, 3/10% KCL, 3/10% D-108, 2/10% D-65, 25 sacks 75-25 Poz-fill, .2% D-46 & 5 gallons D-58 ahead of 400 sacks 50-50 Poz, 3/10% D-108, 2/10% D-65, .2% D-46 & 3#/sack KCL. PD 3:15 AM 9-13-80. WOC 12 hrs. Ran Temperature Survey and found top of cement at 2100'. WOC and tested to 1500#, OK. Rigged up pulling unit. Circulated hole w/2% KCL. WIH w/casing gun on wireline and perforated 3958-64' w/12 .50" holes (2 SPF). Packer set at 3892'. Swabbed well dry. Acidized perfs 3958-64' w/2000 gallons 10% Morrowflow acid and nitrogen. Flowed well back and swabbed dry in 3 runs. Sand frac'd perforations 3958-3964' w/20000 gallons Titan II-30 gel using 45250# sand and CO2. Recovered load and stabilized at 185 psi on 1/2" positive choke = 1240 mcfpd.

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18. I hereby certify that the foregoing is true and correct	October 7 1980	
SIGNEDKTall TITLE Engineer DATE .	000000000000000000000000000000000000000	
ACCEPTED FOR RECORDIS Space for Federal or State office use) APPROVED BY		
U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO *See Instructions on Reverse Side		