ストレレンマにしか STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT SEP 26 1980 MB. BY COMITS ACCEIVED OIL CONSERVATION DIVISION DISTRIBUTION P. O. BOX 2088 O. C. D. Form C-103 SANTA FE Revised 19-1-78 SANTA FE, NEW MEXICO 87501 ARTESIA, OFFICE FILE Sa. Indicate Type of Lease U.1.G.1. LAND OFFICE State 500 X OPERATOR 5. State Oli & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS BY PARTY OF PROPOSALS TO BALLE OF TO DEEPEN OF PLUG BACK TO A DIFF 7. Unit Agreement Name OTHER-2. Name of Operator 8. Farm or Lease Name McClellan Oil Corporation (Yates Petroleum Corp. - Agent) Johnson Fee 3, Address of Operator 9. Well No. 207 So. 4th St., Artesia, NM 88210 4. Location of Well 10. Field and Pool, or Wildcat Wildcat Abo 1980 South UNIT LETTER West 30 26E 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3719.7' GR Chaves Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK REMEDIAL WORK HODHAEL VIJAROOM COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Spudded a 17-1/2" hole at 5:00 PM 9-13-80. TD 40' TD 455' Ran 11 joints of 13-3/8" 54.5# J-55 ST&C (456.86') of casing set at 456'. 1-shoe joint set at 455'. Flapper float at 418'. Cemented w/450 sacks Class C 3% CaCl. Slurry weight 14.8, 1.32 cu ft/ sack. Compressive strength at 70 degrees, 1023 psi in 12 hours. PD 9:15 AM 9-15-80. Cement circulated 25 sacks to pits. WOC 12 hours. Reduced hole to 12-1/4". Drilled plug and tested to 600#, OK. Resumed drilling. TD 1874' Ran 26 joints 8-5/8" 24# J-55 (1002.72') of casing set at 1002'. I-notched guide shoe at 1002'. Flapper insert float at 967'. Cemented w/400 sacks 65-35 Poz, 4% Bentonite and 7# Kolite, 1/4# celloflakes and 3% CaCl. Tailed in w/150 sacks Class C 2% CaCl. PD 9:45 AM 9-17-80. Cement circulated 50 sacks to pit. WOC 18 hours. Nippled up and tested to 1500#, OK. Reduced hole to 7-7/8". Drilled plug and tested to 600#, OK. Resumed drilling.

8.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.

Sept. 25, 1980

PRADVED BY

SUPERVISOR, DISTRICT II

DATE SEP 3 0 1980

ONDITIONS OF APPROVAL, IF ANY: