

UNIT STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC  
(Other instructions o.  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ WELL GAS ☒ WELL OTHER ☐

2. NAME OF OPERATOR MESA PETROLEUM CO ✓

3. ADDRESS OF OPERATOR 1000 VAUGHN BUILDING/MIDLAND, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface 1980' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3823.9' GR

5. LEASE DESIGNATION AND SERIAL NO. NM - 14993

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME SAVAGE FEDERAL

9. WELL NO. 2

10. FIELD AND POOL, OR WILDCAT UNDESIGNATED ABO

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC 4, T7S, R25E

12. COUNTY OR PARISH CHAVES

13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Spudding & 13 3/8" Csg

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded well with 17 1/2" hole on 10-9-80 and drilled to 866'.  
Ran 21 jts 13 3/8", 48#, H-40 casing, set at 866' with FC at 832'.  
Cemented with 200 sx Thix-Set + 1/4# Flocele followed by 600 sx Lite + 1/4# Flocele and tailed in with 200 sx "C" + 2% CaCl. Circulated 225 sx to pit. WOC 8 hours, tested casing to 500 psi - OK. Reduced hole to 11" and drilled ahead on 10-15-80.

RECEIVED

OCT 21 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

R. E. Mathis

TITLE

Regulatory Coordinator

DATE

10-17-80

(This space for Federal or State office use)

APPROVED BY

R. Chester

TITLE

DATE

CONDITIONS OF APPROVAL

OCT 23 1980

XC: USGS (6) TLS, HOBBS OFFICE, CEN RCDS, ACCTG, JBH, MEC, PARTNERS, FILE

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side