

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-14993

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

MESA PETROLEUM CO ✓

3. ADDRESS OF OPERATOR

1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' FNL & 1980' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

SAVAGE FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

UNDESIGNATED ABO

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 4, T7S, R25E

12. COUNTY OR PARISH 13. STATE

CHAVES

NEW MEXICO

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3823.9' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other) 8 5/8" casing & cement

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 11" hole to 1740' on 10-19-80. Ran 44 jts 8 5/8", 24#, K-55 casing, set @ 1739' with FC at 1662'. Cemented with 100 sx Thix-Set + 1/4# Flocele + 2% CaCl, tailed in with 200 sx "C" + 2% CaCl. Cement did not circulate. WOC 13 hours. Reduced hole to 7 7/8" and tested BOP's & casing to 600 psi for 30 minutes - OK. Drilled ahead on 10-20-80.

RECEIVED
OCT 27 1980
O. C. D.
ARTESIA OFFICE

ACCEPTED FOR RECORD
OCT 28 1980
U.S. GEOLOGICAL SURVEY
ROSEBUD, MONTANA

RECEIVED
OCT 22 1980
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED R. E. MarkTITLE Regulatory CoordinatorDATE 10-21-80

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

XC: USGS (6), TLS, HOBBS OFFICE, MEC, PARTNERS, FILE

*See Instructions on Reverse Side