

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYPHIL. O. D. COPY  
SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.  
3. LEASE DESIGNATION AND SERIAL NO.

NM 12101

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Fred Pool, Jr.		7. UNIT AGREEMENT NAME Rio Felix
3. ADDRESS OF OPERATOR Clovis Star Rt. Box 1300 Roswell, N.M. 88201		8. FARM OR LEASE NAME Rio Felix
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FNL; 1980 FEL Sw - NE		9. WELL NO. 1
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Wildcat
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3654. 01		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 25-14S-24E
		12. COUNTY OR PARISH Chaves
		13. STATE N.M.

## 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) surface casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

July 11, 1981

Set 1093 ft. 9 5/8 casing. Used 600 sx Class C cement, 27 Cal. Chloride  
Cement did not circulate. Ran temperature survey, showed top of cement at  
220 ft. from surface. Cement was one inch to surface with 300 sx cement.  
W O C 36hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Anta Pool*

TITLE

Secretary

DATE

7-15-81

(This space for Federal or State office use)

ROGER A. CHAPMAN

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

JUL 27 1981

TITLE

DATE

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side