

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5018	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		White Draw Unit	
C & K Petroleum, Inc. ✓		8. Farm or Lease Name	
3. Address of Operator		White Draw Unit	
P. O. Drawer 3546, Midland, TX 79702		9. Well No.	
4. Location of Well		1	
UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM		10. Field and Pool, or Wildcat	
THE East LINE, SECTION 14 TOWNSHIP 3-S RANGE 27-E NMPM.		Wildcat Abo	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4008 GR		Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>
		Completion Attempt	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103

- 1/28/81 - B.P. 4830'. Perf 4776-78-80-82-86-99-4802-04-06-10, 10 holes. Set Pkr. at 4741.
- 1/29/81 - Acidize perf w/4000 gal. acid, 1000 SCF N2 per bbl. Flow back N2 & acid wtr. Rec. load wtr. No new water. No show oil or gas. Perf. 4776-4810. Non Productive.
- 2/3/81 - B.P. @4708'. Perf. 4679-80-81-86-87-88-89-90-91-92, 10 holes. Pkr. 4642'.
- 2/4/81 - Acidize perf 4679 to 4692 w/2000 gal. w/1000 SCF N2 per bbl. Flow back 9 BLW & N2 & died. Swab tbg. dry. No show oil or gas. Suspected B.P. leaking.
- 2/5/81 - Released pkr., lower & reset to test B.P. @ 4708'. Found B.P. down hole, 4727, would not hold. B.P. leaked while treating perf. 4679-4692.
- 2/6/81 - Rerun B.P. & pkr. Set B.P. @ 4716. Test to 3000 psi. Set pkr. @ 4642. Reacidize perf 4679-4692 w/2000 gal acid & 1000 SCF N2. Flow back 62 BLW & N2 plus 3 BNW.
- 2/7/81 - Left open to test tank 15 hrs. Overnite flow back 45 BW, no oil or gas. Load was 62 plus 48 BNW.
- 2/8/81 - Run swab 3 trips. Swab 12 BNW. No show oil or gas. Perf 4679-4692 are water bearing. No shows oil or gas. Pulled tubing, packer & B.P. out of hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lunella Zeeck TITLE Administrative Supervisor DATE 2/10/81

APPROVED BY Mike Wilkman TITLE GEN. AND. GAS INSPECTOR DATE FEB 12 1981

CONDITIONS OF APPROVAL, IF ANY: