

SANTA FE, NEW MEXICO 87501

MAR 10 1981

O. C. D.

ARTESIA, OFFICE

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐5. State Oil & Gas Lease No.
L-6274

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERFORATE OR PLUG, OR TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL OR REPERFORATE OR PLUG" FOR SUCH PROPOSALS.OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator

Yates Petroleum Corporation

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER M 710 FEET FROM THE South LINE AND 660 FEET FROM

THE West LINE, SECTION 32 TOWNSHIP 5S RANGE 25E NMPS.

7. Unit Agreement Name

8. Name of Lease Name

Dee OQ State

9. Well No.

1

10. Field and Pool, or Wildcat

Und. Abo

15. Elevation (Show whether DF, RT, GR, etc.)

3793.3' GR

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐REPERFORATE OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☐CHANGE PLANS ☐☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPS. ☐CASING TEST AND CEMENT JOBS ☒OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 17-1/2" hole at 9:00 PM 2-23-81.

TD 463'. Ran 10 joints of 13-3/8" 54.50# K-55 casing set at 463'. 1-Regular Pattern guide shoe at 434'. Flapper insert float set at 387'. Cemented w/450 sacks Class C 4% Cacl. Compressive strength at 70 degrees 1023 psi in 12 hours. PD 3:45 PM 2-24-81. Cement circulated 55 sacks. WOC 12 hours. Reduced hole to 7-7/8". Bumped plug to 500 psi - held 5 minutes.

TD 4500'. Ran 112 joints of 4-1/2" 9.5# J-55 ST&C casing set at 4497'. 1-diff fill shoe at 4497'. 1-diff fill shoe float at 4497'. Cemented w/375 sacks 50-50 Poz, .6% D-112, .3% D-65 Tic and 3# KCL/sack. PD 7:00 AM 3-7-81. Bumped plug to 1500 psi, released pressure and float held okay. WOC. Ran Temperature Survey and found top of cement at 2600'. PBTD 4686'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature of Maria Rodarte

TITLE Engineering Secretary

DATE 3-10-81

APPROVED BY

Signature of W.A. Gussitt

TITLE SUPERVISOR, DISTRICT II

DATE

MAR 12 1981

CONDITIONS OF APPROVAL, IF ANY:

Post ID
3-10-81
3-12-81