

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

Form C-103
Revised 10-1-

AMENDED*

APR 02 1981

5a. Indicate Type of Lease	State ☒ ☐	For ☐
5. State Oil & Gas Lease No.	L-6274	

SUNDY NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "I" FORM (C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☒	OTHER ☐	7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation			8. Farm or Lease Name Dee OQ State
Address of Operator 207 South 4th St., Artesia, NM 88210			9. Well No. 1
Location of Well UNIT LETTER M 710 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 5S RANGE 25E NMPL.			10. Field and Pool, or Whdeat Und. Abo
15. Elevation (Show whether DF, RL, GR, etc.) 3793.3' GR			12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
REPAIR ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	OTHER ☐

7. Descriptive Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 17-1/2" hole at 9:00 PM 2-23-81.

TD 463'. Ran 10 joints of 13-3/8" 54.50# K-55 casing set at 463'. 1-Regular Pattern guide shoe at 434'. Flapper insert float set at 387'. Cemented w/450 sacks Class C 4% Cacl. Compressive strength at 70 degrees 1023 psi in 12 hours. PD 3:45 PM 2-24-81. Cement circulated 55 sacks. WOC 12 hours. Reduced hole to 7-7/8". Bumped plug to 500 psi - held 5 minutes.

TD 4500'. Ran 112 joints of 4-1/2" 9.5# J-55 ST&C casing set at 4497'. 1-diff fill shoe at 4497'. 1-diff fill shoe float at 4497'. Cemented w/375 sacks 50-50 Poz, .6% D-112, .3% D-65 Tic and 3# KCL/sack. PD 7:00 AM 3-7-81. Bumped plug to 1500 psi, released pressure and float held okay. WOC. Ran Temperature Survey and found top of cement at 2600'. PBDT 4481'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Gonzalez</u>	TITLE <u>Engineering Secretary</u>	DATE <u>3-10-81</u>
APPROVED BY <u>W.A. Gussert</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>APR 06 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		