

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

JUN 12 1981

O. C. D.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-0336	

SUNDRY NOTICES AND REPORTS ON WELLS, ARTESIA OFFICE  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- P&A
Name of Operator Yates Petroleum Corporation /		
Address of Operator 207 South 4th St., Artesia, NM 88210		
Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 4S RANGE 24E NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name Redman "OY" State
9. Well No. 1
10. Field and Pool, or Wildcat Und. Abo
12. County Chaves

15. Elevation (Show whether DF, RT, GR, etc.)  
3964.3' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
ILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Plug & Abandon <input checked="" type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1D 1318'. Plugged well as follows: Spotted 50 sacks Class "C" Neat cement. PD 2:02 AM 5-14-81. WOC 2 hrs. Tagged cement at 473'. Spotted 200 sacks Class "C" Neat cement. PD 4:42 AM 5-14-81. WOC 2 hrs. Tagged cement at 473'. Spotted 250 sacks Class "C" Neat cement. PD 6:50 AM 5-14-81. WOC 1 hr. Tagged cement at 423'. Spotted 100 sacks Class "C" Neat cement. PD 8:01 AM 5-14-81. WOC 1 hr. Tagged cement at 423'. Spotted 50 sacks Class "C" Neat cement. PD 8:41 AM 5-14-81. WOC 1 hr. Tagged cement at 423'. Spotted 50 sacks Class "C" Neat cement at 418'. Spotted 200 sacks Class "C" Neat cement. PD 10:30 AM 5-14-81. WOC 2 hrs. Tagged at 40'. Plugged & abandoned. Skidded rig to Redman "OY" State #1-Y.

Regulation abandonment marker will be installed upon completion of Redman "OY" State #1-Y. Verbal approval for plugging and skidding rig obtained from Mr. Gressett, OCD, Artesia, on May 12, 1981.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE Engineering Secretary DATE 6/11/81

APPROVED BY J. M. Williams TITLE OIL AND GAS INSPECTOR DATE JUN 16 1981

CONDITIONS OF APPROVAL, IF ANY: