

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
Yates Petroleum Corporation ✓
3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FNL & 1650' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
- |                      |                          |                                     |
|----------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF  | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| FRACTURE TREAT       | <input type="checkbox"/> | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE     | <input type="checkbox"/> | <input type="checkbox"/>            |
| REPAIR WELL          | <input type="checkbox"/> | <input type="checkbox"/>            |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/>            |
| MULTIPLE COMPLETE    | <input type="checkbox"/> | <input type="checkbox"/>            |
| CHANGE ZONES         | <input type="checkbox"/> | <input type="checkbox"/>            |
| ABANDON*             | <input type="checkbox"/> | <input type="checkbox"/>            |
| (other)              |                          |                                     |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 14-3/4" hole at 9:00 PM 4-6-81. TD 200'- Ran 5 joints of 10-3/4" 35.50# K-55 ST&C casing set at 200'. 1-notched guide shoe at 200'. Flapper float insert at 160'. Cemented w/100 sacks 65-35 Poz, 4% Bentonite, 8# Kolite, 1/4# celloflakes and 3% CaCl. Tailed in w/100 sacks Class C Neat 2% CaCl. Compressive strength of cement - 500 psi in 12 hours. PD 10:49 AM 4-7-81. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 25 sacks. WOC 16 hours and 10 minutes. Reduced hole to 9-1/2". Drilled plug and resumed drilling.

5. LEASE  
NM-277916
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
North Sturgeon "PR" Federal
9. WELL NO. 1
10. FIELD OR WILDCAT NAME  
LINDA End. San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit C, Sec. 4-T7S-R26E
12. COUNTY OR PARISH  
Chaves
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3657.2' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

APR 23 1981

O. C. D.  
ARTESIA, OFFICE

APR 20 1981

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Roger A. Chapman TITLE Engineering Secretary DATE 4-16-81

ACCEPTED FOR RECORD (This space for Federal or State office use)  
APPROVED BY Roger A. Chapman TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

APR 22 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side