



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

03-Dec-01

SOUTHEASTERN PETROLEUM INC
~~PO BOX 1893~~ 3000 N. Washington
ROSWELL, NM ~~88201~~
88201

Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

POGO STATE 001		P-16-7S-28E	30-005-60915-00-00	3/26/02 NIC		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/29/2001	Routine/Periodic	Mike Bratcher	Yes	No	3/3/2002	MLB0133727989
Comments on Inspection:		Well is in violation of Rule 201 requiring idle wells to be properly abandoned.				
POGO STATE 002		N-16-7S-28E	30-005-61241-00-00	3/26/02 NIC		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/29/2001	Routine/Periodic	Mike Bratcher	Yes	No	3/3/2002	MLB0133728220
Comments on Inspection:		Well is in violation of Rule 201 requiring idle wells to be properly abandoned.				
11/29/2001	Routine/Periodic	Mike Bratcher	Yes	No	3/3/2002	MLB0133728351
Comments on Inspection:		Tank Battery is leaking. Violation Rule 116.				