

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 49-E1424
5. LEASE DESIGNATION AND SERIAL NO.

NM-18821

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Haystack Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Wildcat Montoya

11. SEC., T., S., M., OR BLK. AND
SURVEY OR AREA

Sec. 26-5S-26E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	15. ELEVATIONS (Show whether DF, RT, OR, etc.)
2. NAME OF OPERATOR Read & Stevens, Inc. ✓	3986.4'
3. ADDRESS OF OPERATOR P.O. Box 1518, Roswell, NM 88201	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FWL	
14. PERMIT NO. -	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-24-81 RU Welex, perf 6548'-6562', 14', 2 shots/ft, 28 holes, .38" diam. TIH w/ tbg, spot acid across perfs, PU, set pkr @ 6461', pres annulus to 900psi, acidize w/ 1000gals 15% MCA w/ 35-7/8" ballsealers. Form. broke @ 3500psi, avg 2850psi @ 2.2 BPM, ISIP 2200psi, 10 min 1400psi, 15 min 1250psi, 50.4 BLTR, swbd 49 BBLs, swbd down, SION.

ACCEPTED FOR RECORD
ROGER A. CHAPMAN

JUL 2 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICORECEIVED
JUN 30 1981
OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Bruce Stubbins*

TITLE Drilling & Production Mgr DATE 6-26-81

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

