

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-RJ424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
MESA PETROLEUM CO./

3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 3025' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*

SUBSEQUENT REPORT OF:

RECEIVED
SEP 11 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

(other) SPUD, 13 1/2" csg & cement

5. LEASE
NM-28298

6. IF INDIAN, ALLOTTEE OR TRIBE NAME RECEIVED

7. UNIT AGREEMENT NAME
SEP 16 1981

8. FARM OR LEASE NAME
ASKEW FEDERAL O. C. D.

9. WELL NO. ARTESIA, OFFICE
1

10. FIELD OR WILDCAT NAME
UNDESIGNATED ABO

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
SEC 18, T6S, R24E

12. COUNTY OR PARISH 13. STATE
CHAVES NEW MEXICO

14. AP. NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3942.5' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded well with 17 1/2" hole on 8-28-81. Drilled to 875' on mud and ran 23 jts 13 3/8", 48#, K55 casing set at 865'. Cemented with 800 sx HLW + 1# Flocele + 4% CaCl, 300 sx Thixset + 4% CaCl, and tailed in with 200 sx "C" + 2% CaCl. Cement did not circulate. Set seven plugs with a total of 960 sx Thixset + 4% CaCl to circulate cement. Reduced hole to 11" and drilled ahead on 9-2-81.

NOTE: Hit 250 B/H Brackish water at 910'.

AC: USGS (6), TLS, GEN. RCDS, ACCTG, MEC, LAND, PARTNERS, ROSWELL, FILE
Subsurface Safety Valve Model and Type Set @

18. I hereby certify that the foregoing is true and correct

SIGNED R. S. [Signature] REGULATORY COORDINATOR DATE 9-4-81

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY

SEP 14 1981

TITLE DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO