

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☒

O. C. D.

2. NAME OF OPERATOR
Yates Petroleum Corporation

ARTESIA, OFFICE

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650 FNL & 990 FEL, Sec. 10-8S-25E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☒
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM 18483

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Morton SZ Federal

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

U.S. Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit H, Sec. 10-T8S-R25E

12. COUNTY OR PARISH

Chaves

13. STATE

NM


14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3636.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole at 11:45 AM 6-8-82. Set 80' of 20" conductor pipe. Ran 21 joints of 10-3/4" 48# casing set at 845'. 1-Texas Pattern guide shoe set 845'. Insert float set 805'. Cemented w/400 sacks Pacesetter Lite with 1/4# celloseal, 3% CaCl. Tailed in w/300 sacks Class "C" with 3% CaCl. Compressive strength of cement - 1250 psi in 12 hours. PD 1:15 AM 6-10-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC. Drilled out 7:15 PM 6-10-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.



Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Antonio Goodlett

TITLE Engineering Secty

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
DATE 6-11-82

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JUN 30 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO