RECEIVED

Artesia, MI 88210

NOV 1 6 1982

Form Approved.

Form 9-331 Dec. 1973

Production

PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON\*

(other)

Casing

Dec. 1973	Bud Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE ARTESIA, OFFICE NM-12438
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil	Bravo Federal
well gas X other	9. WELL NO.
2. NAME OF OPERATOR	5
Western Reserves Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Pecos Slope (Abo)
P. O. Box 993 Midland, TX 79702	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 30, T-6-S, R-25-E
AT SURFACE: 1980' FNI. & 1904' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Chaves NM
AT TOTAL DEPTH: same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
OURSES AND ADDRESS OF THE PROPERTY OF	3776.6
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
A D A A I D C A I +	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-7-82 Ran 91 jts. of K-55 10.5#, 4 1/2" casing. Set at 3796'. D.V. tool set at 1470'. Cemented first stage with 250 sx Class "C" 2% KCl. Plug down on first stage at 6:30 pm. Full circulation. Open D.V. tool and cemented with 500 sx Halliburton Lite. Had full circulation throughout job. Plug down at 7:30. Rig released at 10:00 PM 11-7-82. Ran temperature survey top of cement at 250' from surface.

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	First Control of the
SIGNED BY ORDER Agent for W.R.	
ACCEPTED FOR RECORDING Space for Federal or State office use)  (ORIG. SGD.) DAVID R. GLASS  ITLE	DATE MONEY E 10001
CONDITIONS OF APPROVACE AND 1982	TO BUS
U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO See Instructions on Reverse Side	AMERICA CONTRACTOR STRAIGE