

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
McClellan Oil Corporation ✓
3. ADDRESS OF OPERATOR
P.O. Drawer 730, Roswell, NM 88202
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FSL & 1980' FWL
AT TOP PROD. INTERVAL: *wt. R*
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | | SUBSEQUENT REPORT OF: | |
|---------------------------|--------------------------|-----------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | | <input type="checkbox"/> |
| (other) Cement and casing | | | |

5. LEASE
NM-35925
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME RECEIVED
8. FARM OR LEASE NAME Dana Federal OCT 18 1982
9. WELL NO. 4 O. C. D.
10. FIELD OR WILDCAT NAME ARTESIA, OFFICE
Pecos Slope Abo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 3-T9S-R25E
12. COUNTY OR PARISH Chaves 13. STATE NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3549' G.L.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/05/82: Spudded with 12½" bit with Tex-Mex Rig #3.

10/08/82: Drilled to 906'. Ran 896' of 8-5/8" 24# new casing. Cemented with 300 sx BJ Lite with ¼# celloflake, 2% CaCl₂ and 300 sx Class "C" with 2% CaCl₂. Circulated 100 sx. WOC - 18 hours. Nipple up BOP's. Test to 500 psi for 30 min.

RECEIVED
(OCT 12 1982)

Subsurface Safety Valve: Manu. and Type

OIL & GAS
MINERALS & T. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *David R. Glass* (ACCEPTED FOR RECORD) TITLE Operations Manager DATE October 8, 1982

APPROVED BY (ORIG. SGD.) DAVID R. GLASS (This space for Federal or State office use)
OCT 14 1982
CONDITIONS OF APPROVAL, IF ANY: TITLE DATE

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side