Form 9-331 Dec. 1973 UNITED STATES Artesia, NM 8321 DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42-R1424 5. LEASE NM 38342 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deeped or plug back BCENED reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other DEC 9 1982 2. NAME OF OPERATOR STEVENS OPERATOR OF C.D. 3. ADDRESS OF OPERATOR P. O. Box 2408, Roswell, NM 88201 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	2 10. FIELD OR WILDCAT NAME <u>Pecos Slope Abo</u> 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 9, T-7-S, R-26-E</u> 12. COUNTY OR PARISH <u>Chaves</u> <u>NM</u>
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7657.2 GK
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	

11-18-82 Ran 114 joints 4¹/₂" x 10.5# casing. Set & cement @ 4590' w/475 sxs Class "H" w/2% CC. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease. Reached total depth @ 4590'.

11-19-82 Ran temp. survey & shows top of cement @ 2550'. PBTD 4543'.

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct Production SIGNED IN TITLE Coordinator	DATE December 3, 1982
AUGEFIED FUR RECORD	
(ORIG. SGD.) DAVID R. GLASS CONDITIONS OF APPROVALE AN 8 1982	
MINERALS MANAGEMENT SERVICE ROSWELL, NEW MEXICO	CEO 7 1082
*See Instructions on Reverse Side	
	RUGUELL, N. 17 MERIOE